Tello Release Notes

Date:	2019.03.28
Aircraft Firmware:	v01.04.88.01

What's New?

- Optimized aircraft performance.

Notes:

- Do not power off the aircraft during the firmware update.

- Restart the aircraft once the firmware update is complete.

- If the firmware update fails, restart the aircraft and the Tello app, and retry.

https://www.ryzerobotics.com/

Tello Release Notes

Date:	2018.12.11
Aircraft Firmware:	v01.04.78.01

What's New?

- Increased the hover accuracy for auto takeoff.

- Added support for Swift Playgrounds.

Notes:

- Do not power off the aircraft during the firmware update.

- Restart the aircraft once the firmware update is complete.

- If the firmware update fails, restart the aircraft and the Tello app, and retry.

Tello Release Notes

Date :	2018.08.16
Aircraft Firmware :	v01.04.35.01

What´s New?

- Increased maximum flight altitude to 30 m.

Notes:

- Do not power off the aircraft during the firmware update.

- Restart the aircraft once the firmware update is complete.

- If the firmware update fails, restart the aircraft and the Tello app, and retry.

Tello Release Notes

Date :	2018.05.03
Aircraft Firmware :	v01.03.33.01

What's New?

- Optimized aircraft performance after a collision. Motors will now stop when the threshold is triggered.

- Added additional tips in the app for aircraft calibration.

- Optimized user experience when using with GameSir T1D Bluetooth controller.

Notes:

- Do not power off the aircraft during the firmware update.

- Restart the aircraft once the firmware update is complete.

- If the firmware update fails, restart the aircraft and the Tello app, and retry.

https://www.ryzerobotics.com/

Tello Release Notes

Date :	2018.03.20
Aircraft Firmware :	v01.03.18.01

What´s New?

- Optimized Throw & Go performance.

- Optimized 8D Flips performance.

- Improved wind resistance performance.

- Optimized video transmission performance.

- Optimized user experience when using with GameSir T1D Bluetooth controller.

Notes:

- Do not power off the aircraft during the firmware update.

- Restart the aircraft once the firmware update is complete.

- If the firmware update fails, restart the aircraft and the Tello app, and retry.

https://www.ryzerobotics.com/