

Tello Release Notes

Date :	2018.05.03
Aircraft Firmware :	v01.03.33.01

What 's New?

- Optimized aircraft performance after a collision. Motors will now stop when the threshold is triggered.
- Added additional tips in the app for aircraft calibration.
- Optimized user experience when using with GameSir T1D Bluetooth controller.

Notes:

- Do not power off the aircraft during the firmware update.
- Restart the aircraft once the firmware update is complete.
- If the firmware update fails, restart the aircraft and the Tello app, and retry.

Tello Release Notes

Date :	2018.03.20
Aircraft Firmware :	v01.03.18.01

What 's New?

- Optimized Throw & Go performance.
- Optimized 8D Flips performance.
- Improved wind resistance performance.
- Optimized video transmission performance.
- Optimized user experience when using with GameSir T1D Bluetooth controller.

Notes:

- Do not power off the aircraft during the firmware update.
- Restart the aircraft once the firmware update is complete.
- If the firmware update fails, restart the aircraft and the Tello app, and retry.